A-TEX INSPECTS

PROFESSIONAL REAL ESTATE INSPECTIONS

ROBERT WELCH, PRI

3613 PINE VALLEY DRIVE, PEARLAND, TX 77581

281-992-9246

TREC LICENSE # 9292

robert@atexinspects.com

ATEXINSPECTS.COM



ALL REFERENCES TO THE PROPERTY ARE ORIENTATED AS ONE WOULD FACE THE FRONT DOOR

INSPECTION DATE

Tuesday, November 18, 2014

CLIENT'S NAME

John & Jane Doe

PROPERTY ADDRESS

1234 Inspection Lane, Houston, TX

REPORT IDENTIFICATION

PROPERTY INSPECTION REPORT

Prepared For:	John & Jane Doe			
	(Name of Client)			
Concerning:	1234 Inspection Lane, Houston, TX			
	(Address or Other Identification of inspected Property)			
Ву:	ROBERT WELCH TREC # 9292	11/18/2014 22:47		
	(Name and License Number of Inspector)	(Date)		

The inspection of the property listed above must be performed in compliance with the rules of the Texas Real Estate Commission (TREC).

The inspection is of conditions which are present and visible at the time of the inspection, and all of the equipment is operated in normal modes. The inspector must indicate which items are in need of repair or are not functioning and will report on all applicable items required by TREC rules.

This report is intended to provide you with information concerning the condition of the property at the time of inspection. Please read the report carefully. If any item is unclear, you should request the inspector to provide clarification.

It is recommended that you obtain as much history as is available concerning this property. This historical information may include copies of any seller's disclosures, previous inspection or engineering reports, reports performed for or by client(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Year Built -	2002	Property Type -	Single Family
Sq Footage -	3048 SF	Design -	Two Story
_		Orientation -	Southwest
Weather -	Clear and Dry	_	_
Temperature -	80 Degrees	Utilities -	All On
Attending	Client Buyer's Agent	Occupied	No
-	zajo. o rigorit	•	

This report contains addendum pages and pictures that are required to remain with the TREC format pages in order to constitute a complete inspection report.

The report remains the property of the documented client and the inspection company. The information herein is not transferable and shall not be released to unauthorized personnel without the express approval the inspection company.

Further information on the Scope of the Inspection and Limits of Liability can be found in the Inspection Contract.

Report Identification:	1220200845Y
------------------------	-------------

Additional pages may be attached to this report. Read them very carefully. This report may not be complete without the attachments. If an item is present in the property but is not inspected, the "NI" column will be checked and an explanation is necessary. Comments may be provided by the inspector whether or not an item is deemed in need of repair

I= In	specte	d	NI= Not	Inspected	NP= Not Present	R= Not functioning or In Need of Repair
I	NI	NP	R			Inspection Item
			I.	STRUCT	URAL SYSTEMS	
X						space areas are not inspected, provide an explanation) in performance is mandatory.)
				Crav	Foundation Type: Floor Structure: vlspace Insp Method:	Concrete
				See	Structural addendum p	ages for additional comments.
					• • • • • • • • • • • • • • • • • • • •	ory at the time of inspection - Defects, e no significant impact or are cosmetic.
X				_	ing and Drainage	
				See	Structural addendum p	ages for additional comments.
X					Covering (If the roof nments	is inaccessible, the method used to inspect.)
					Structural addendum p Method of Inspection: Type of Covering:	
X			X	_	Structure & Attic (If the attic is inaccessible, the method used to inspect.)
				X See	Structural addendum p	ages for additional comments.
				Appr	f & Ceiling Structure: Method of inspection: Insulation Type: rox. Insulation Depth: oor barrier Observed:	Entered - (inspection limited due to obstructions, framing, equipment, insulation, etc.) Fiberglass Average 9 to 11"
				tempe	-	are and attic is limited due to access, insulation, equipment, attic ot moved, mobility may be limited. Vapor barriers may not be visible during
X			X		(Interior and Exter	ior)
				X See	Structural addendum p	ages for additional comments.
				Ty	Type of Structure: pe of Wall Cladding: Type of Columns:	Framed Combination of Brick Veneer, Hardy Siding & Stone Framed

					-1	
I= In	specte	il	NI=1	Not Inspected NP= Not Present	R= Not functioning or In No	eed of Repair
ı	NI	NP	R		Inspection Item	
×			X	F. Ceilings and Floors Comments		
				See Structural addendum p	pages for additional comments.	
X			X	G. Doors (Interior and Ext Comments	erior)	
				See Structural addendum p	pages for additional comments.	
X				H. Windows Comments		
				See Structural addendum p	pages for additional comments.	
				Window Type:	Multi Pane	
X				I. Fireplace/Chimney Comments		
				See Structural addendum p	pages for additional comments.	
X				J. Porches, Decks and Ca Comments: Patios, Stairs a	rports (Attached) nd Garage Fire Separation are include	ed in this section
				See Structural addendum p	pages for additional comments.	
X				K. Other Comments		
				See Structural addendum p Walkways Driveways Fences/Gates	pages for additional comments.	
				II. ELECTRICAL SYSTEMS		
×				A. Service Entrance and F Comments	Panels	
				See Electrical addendum p	ages for additional comments.	
				Amps: Service and Voltage Type: Service Conductor Type: Main Panel Location: Sub Panel Location:	Copper Garage	120/240 volts Select Other Locations Select Other Locations

Repo	rt Ident	ificatio	n: 122 0	0200845Y		
I= In	specteo		NI= Not I	nspected NP= Not Present	R= Not functioning or In N	eed of Repair
<u> </u>	NI	NP	R		Inspection Item	_
X			X	B. Branch circuits - Conn repair the lack of ground Comments	ected devices and Fixture definition in the fault circuit protection where	
				See Electrical addendum p	pages for additional comments.	
				Distribution Wire Type	: Copper	
				Romex Cloth Wrapped Other	Knob and Tube	Emt / Rigid Conduit Type Flexible Conduit Type
				Aluminum Branch Wiring Ob GFCI's not installed at curre		
			III.	HEATING, VENTILATIO	N AND AIR CONDITIO	NING SYSTEMS
X			X	A. Heating Equipment Comments		
				Type and Energy Source	Electric Gas	Oil Other
				Forced Air Radiant Other	Hydronic Heat Pump	Baseboard Geo-thermo
				See Heating/Cooling adde	ndum pages for additional com	ments.
				X Attic Additional Locations	Additional Locations Additional Locations	Additional Locations Additional Locations
X			X	B. Cooling Equipment: Comments		
				Type and Energy Source	Electric Gas	Other
				X Electric Evaporative	Heat Pump Window	Geo-thermo Other
				See Heating/Cooling adde	ndum pages for additional com	ments.
				Exterior Additional Locations	Additional Locations Additional Locations	Additional Locations Additional Locations
X			X	B. Ducts and Vents Comments		
				See Heating/Cooling adde	ndum pages for additional com	ments.
				Filter Location		
			IV.	PLUMBING SYSTEM		
X			X	A. Water Supply System a	and Fixtures	
				See Plumbing addendum	pages for additional comments.	

1220200845Y Report Identification: NI= Not Inspected NP= Not Present R= Not functioning or In Need of Repair I= Inspected NI NP R Inspection Item The following describes the types of supply and distribution piping observed during the inspection process. Other piping may exist that was not visible at the time of the inspection. Type of Supply Lines: Galvanized Distribution Lines Type: Copper Shutoff Valve Location: West Exterior B. Drains, Wastes, Vents Comments See Plumbing addendum pages for additional comments. The following describes the types of Drain/Waste/Vent piping observed during the inspection process. Other piping may exist that was not visible at the time of the inspection. Drain/Waste/Vent Type: Plastic C. Water Heating Equipment (Report as in need of repair those conditions specifically listed as recognized hazards by TREC rules Energy Source: Gas Size: 2 - 40 gal Comments See Plumbing addendum pages for additional comments. D. Hydro-Therapy Equipment Comments See Plumbing addendum pages for additional comments. V. APPLIANCES $oldsymbol{oldsymbol{ iny}}$ $oldsymbol{oldsymbol{ iny}}$ $oldsymbol{oldsymbol{ iny}}$ A. Dishwasher Comments See Appliances addendum pages for additional comments. **B. Food Waste Disposer** Comments See Appliances addendum pages for additional comments. C. Range Hood Comments See Appliances addendum pages for additional comments. D. Ranges/Ovens/Cook tops Comments See Appliances addendum pages for additional comments. **E. Microwave Cooking Equipment** Comments See Appliances addendum pages for additional comments.

Repo	rt Ident	ificatio	n:	1220200845Y
I= In	specte	d	NI= N	Not Inspected NP= Not Present R= Not functioning or In Need of Repair
ı	NI	NP	R	Inspection Item
		X		F. Trash Compactor Comments
				See Appliances addendum pages for additional comments.
X				G. Bathroom Exhaust Fans and/or Heaters Comments
				See Appliances addendum pages for additional comments.
		×		H. Whole House Vacuum Systems Comments
				See Appliances addendum pages for additional comments.
X				I. Garage Door Operators Comments
				See Appliances addendum pages for additional comments.
×				J. Door Bell and Chimes Comments
				See Appliances addendum pages for additional comments.
×				K. Dryer Vents Comments
				See Appliances addendum pages for additional comments.
×				L. Other Built-In Appliances Comments
				See Appliances addendum pages for additional comments.
				VI. OPTIONAL SYSTEMS
X				A. Lawn Sprinklers Comments
				See Optional Systems addendum pages for additional comments.
X				B. Swimming Pools and Equipment Comments
				See Optional Systems addendum pages for additional comments.
X				C. Outbuildings Comments
				See Optional Systems addendum pages for additional comments.

1220200845Y Report Identification: I= Inspected NI= Not Inspected NP= Not Present R= Not functioning or In Need of Repair NI NP R Inspection Item D. Outdoor Cooking Equipment Energy Source: Gas Comments See Optional Systems addendum pages for additional comments. E. Gas Lines Comments See Optional Systems addendum pages for additional comments. F. Water Wells (A coliform analysis is recommended.) \blacksquare Type of Pump: Select Type of Pump Type of Storage Equipment: Select Type of Storage Equipment Comments See Optional Systems addendum pages for additional comments. G. Septic Systems × Comments See Optional Systems addendum pages for additional comments. H. Security Systems Comments See Optional Systems addendum pages for additional comments. I. Fire Protection Equipment Comments See Optional Systems addendum pages for additional comments. J. Laundry Area Comments Dryer Connection Type: 240 volt electric See Optional Systems addendum pages for additional comments.

I. STRUCTURAL SYSTEMS ADDENDUM PAGES

Report Identification 1220200845Y

The inspection is of the visible portion of the Structural Systems at the time of the inspection. The inspection may be limited by vegetation, possessions, floor covering, limited access, etc. Basement and crawlspace inspections are limited due to obstructions, clearances and installed equipment. Flood potential and soil stability determinations are not part of this inspection. The roof inspection depicts what was visible and accessible to the inspector. It is not a warranty or a guarantee of whether the roof system is watertight or how long it may remain watertight. Past or present leaks are not determined. If conditions are listed a qualified roofing contractor should correct conditions and evaluate the roof system. Ventilation fans, gutters/downspouts are not tested. Standard inspections cover only attached garages and carports. They are not considered habitable, and conditions reported accordingly. Fire separation refers to the walls, doors and ceiling separating the attached garage from the living area of the structure. Fire doors, walls and ceilings are inspected for their safety aspects only in this section. Insure bedroom egress windows remain clear and perform evacuation drills regularly. A representative number of windows are operated, inspection may be limited by window treatments or accessibility. We always recommend re-keying doors for added security. We recommend all chimneys / flues be thoroughly inspected and cleaned by a qualified technician before use. Fireplaces or woodstoves are not ignited during the inspection. If any conditions / defects are noted it is always advisable to have a licensed qualified technician review and or correct the discrepancy.

	A FOI	JNE	OATION:				
	No Faults found in foundation, it is performing as intended and is currently supporting the structure	5					
2	Recommend avoid placing larger growth trees within 20 feet of foundation	6					
3	Maintain ground cover clean of exterior walls and 3-4 inches off top of foundation lip	7					
4	Corner cracks are present, but are considered cosmetic and have no effects on structure support.	8					
	<u> </u>						
	B GRADING AND DRAINAGE:						

	B GRADING AND DRAINAGE:					
1	No faults noted - French drains observed	5				
,	Excellent use of rocks, grading and slope to move water away					
4	from slab	U				
2	Lava rocks used in flower bedding to reduce attraction of	7				
3	wood destroying insects	'				
4	All gutters are visually intact, free of debris and functioning as	0				
4	intended	δ				

C ROOF COVERING:						
	The roof decking is free of deflection, properly supported and functioning as intended.	7				
2	Recommend placing Gutter guards in gutter system to prevent debris build up as home's trees mature.	8				
	Fascia, soffit, eave trim boards and rear eave trim boards are intact and free of any visible defects, warps or decay.	9				
4		10				
5		11				
6		12				

	D ROOF STRUCTURE & ATTIC							
	Garage Attic ladder damaged during installation - replace							
1	damaged ladder and re-insect for functionality.	6						
2	The gap at the 2nd floor attic access door should be properly sealed for fire block protection and energy savings.	7						

3	Limit storage of personal items in attic space above garage to illuminate stress and excessive weigh bearing in this area as noted in item F3 below.	8	
4		9	
5		10	

	E WALLS (Interior and Exterior)				
1	Several wall-ceiling junctions show joint stress and wood frame curing cracks - repairs needed.	7			
2	Recommend painter treat door trims, wall junctions & ceilings for protection.	8			
3	Some cracks were noted that are minor in nature. Small settlement cracks are a common occurrence and can be repaired.	9			
4	Wall in living room has bow in sheetrock - above door to bedroom - repair	10			
5	Hallway wall to first floor bedroom has paint runs	11			
6		12			

		F CEILINGS AND FLOORS				
Γ	1	Ceiling joint to far left of fireplace needs caulking/paint	6			
	/.	Several cracks noted at wall/ceiling junctions in bedrooms and living room, repairs needed.	7			
		Garage ceiling is cracked perpendicular to attic access, which shows excessive stress or inadequate framing - repair shhet rock joints and reinforce framing support in this area.	8			
Γ	4		9			
	5		10			

	G DOORS (Interior and Exterior)				
1	Garage door knob does not fully engage into the door framing	8			
-	and adjoining wall stud, repair for security. Door knob loose between wet bar and formal dining room,				
2	repair of loose hardware needed.	9			
3	Cabinet door hinges to left of stove needs adjustment	10			
	Keep all exterior door's weather stripping and thresholds clean				
4	and free of debris to allow proper sealing and to provide a	11			
	weather tight seal.				
5	Review exterior door caulk sealant every 6 months to ensure proper sealing and protection againt water penetration.	12			
6	Exterior paint repair may be required around door framing and in other high traffic areas to ensure proper weather protection.	13			
7	Trim damaged noted in need of repair at the pantry door.	14			

	H WINDOWS					
1	No Faults Found - All windows are functional, double panes with screens in place	5	Review caulk sealant around exterior and interior window framing every 6 months to repair any sealant shrinkage that may occur to provide proper sealing and weather stripping.			
2	Caulk repair needed around the interior window framing of the formal dining room windows	6				
3	There were secondary window locking mechanisms installed on all 1st floor windows - this is recommend for added home security.	7				
4		8				

	I FIREPLA	ACE	/ CHIMNEY
	No Faults Found - Factory style designed to use both wood	6	
	and propane logs.		
2	Recommend avoid placing flammable items on fire place	7	
	mantle and too close to fire place hearth.	,	
	If gas logs are installed, the fire place vent flue damper should		
3	be secured in the open position to prevent possible closure	8	
	and back-draft of carbon monoxide.		
4		9	
5	Page 11	1 93	4

	J PORCHES, DECKS AND CARPORTS (Attached)					
1	Trim caulk needs repair / painting on the rear porch ceiling area.	7				
	Bow in ceiling trim in center of back porch, resecure bowed ceiling cover and trim.	8				
3	-	9				
4		10				
5		11				
6		12				

	K OTHER					
	FENCING / GATES ——	6	—— DRIVEWAYS / WALKWAYS ——			
	All fencing and gates are functioning as intended	7	No settlement cracks noted at this time in driveways and walkways			
	Self-closing, self-latching gates mechanisms to be used on all gates to pool area.	8	Expansion joints used properly and correctly spaced			
ı	4	9				
	5	10				

REMARKS:

The foundation, roof structure and coverings are functional and intact. See areas in need of repair listed above. Most of the repairs to the walls, ceilings and door trim can be completed by a general contractor.

II. ELECTRICAL SYSTEMS ADDENDUM PAGES

Report Identification 1220200845Y

The inspection is of the visible portion of the Electrical Systems at the time of the inspection. The inspection may be limited by construction phases, visibility of systems and home occupation. Main panels, sub-panels and distribution panels may be limited due to obstructions, clearances and installed equipment. The electrical inspection depicts what was visible and accessible to the inspector. It is not a warranty or a guarantee of whether the electrical system is flawless or that future electrical issues will not occur. The inspector will only be able to comment on evidence of observed past electrical issues or concerns and the possibility of future issues or concerns. If conditions are listed a qualified electrical contractor should correct conditions and evaluate the electrical system. Electrical panels are evaluated for correct wiring types and sizes, current conditions and safety concerns. Outlets are evaluated for safety, GFCI and fire related issues. A representative number of outlets are tested, the inspection may be limited by outlet accessibility. Electrical panels should be correctly labeled. If any conditions / defects are noted it is always advisable to have a licensed qualified technician review and or correct the discrepancy.

	A SERVICE ENTRANCE AND PANELS:				
1	Service entrance and panels are installed within current standards.	5			
2	It is recommended to avoid blocking panel access	6			
3		7			
4		8			

	B MAIN DISCONNECT PANEL				
ľ		Underground service entrance - properly grounded and	4	The main panel neutral and grounding wires are wired	
L		bonded with no visible faults found.		correctly without sharing of the same bus bars.	
	2	Main service breaker, sub-breakers and wiring used is of	5		
		correct sizing for its application.	3		
	2	No evidence of additional wiring additions, no evidence of	6		
	3	double tapping or wire splicing inside main panel.	O		

C SUB-PANELS				
Sub-panel at swimming pool equipment is properly grounded, pumps are bonded and properly wiring is used	3			
Sub-panels at the exterior HVAC units are installed and wired correctly.	4			

	D ELECTRICAL ACCESS					
	Electrical access is on the front side of the right exterior wall. Panel is not obstructed and allows easy access for service.	4				
ſ	2	5				
	3	6				

	E BRANCH CIRCUITS - CONNECTED DEVICES AND WIRING					
1	See wet bar interior electrical note below in section F1.	4				
2		5				
3		6				

	F INTERIOR ELECTRICAL				
	1	The wet bar electrical outlet was not GFCI protected and was	6	All GFCI devices used were properly installed and tested	
	1	loose in its wall junction box.	O	within standards	
	2	All other areas requiring GFCI protection were properly	7		
	4	equipped with GFCI devices	′		
	2	The light in the 2nd floor bath room did not function when	0		
	3	tested.	8		
	4	Utility room light switch needs caulk	9		

	G EXTERIOR ELECTRICAL				
1	All GFCI devices used were properly installed and tested within standards	6			
2	2	7			

H ELECTRICA	L GF	ROUND BONDING
1 All electrical bonding was properly installed and found to be	6	
2	7	

III. HEATING AND COOLING SYSTEMS ADDENDUM PAGES

Report Identification 1220200845Y

The inspection is of the visible portion of the Heating, Ventilation and Air Conditioning Systems at the time of the inspection. The inspection may be limited by vegetation, possessions, limited access, etc. Inspections of systems located in basement and crawlspace are limited due to obstructions, clearances and installed equipment. System inspections include function air flow test to each occupied room. The HVAC inspection depicts what was visible and accessible to the inspector. It is not a warranty or a guarantee of whether the HVAC system is totally flawless or how long it may remain in an operational condition. Past or present repairs are mentioned if detectable. If conditions are listed a qualified HVAC contractor should correct conditions and evaluate the system. HVAC line pressures, leaks and system life expectancies are not part of the standard HVAC inspection. A representative number of air registers will be inspected for function flow, inspection may be limited by electrical supply and accessibility. We recommend all HVAC systems under go periodical cleaning and servicing by a qualified technician. If any conditions / defects are noted it is always advisable to have a licensed qualified technician review and or correct the discrepancy.

	A HVAC	LC	CATIONS				
	1 Attic and Outside - 2 units, one per level 5						
2	Unit was equipped with GFCI outlet	6					
3	Bothe units were level, proper ventilated and installed within	7					
	manufacture's standards	_					
4		8					
	B HEATING SYSTEM						
1	No Faults- Furnace flame was operating correctly	5					
2	Burners were clean and new in appearance	6					
	Safety door shutoff switch was present and operating correctly	7					
4		8					
	C COOL	INC	SYSTEM				
1	Lower left front bedroom vent was not supplying adequate air flow	5	Void (gap) at register in middle bedroom				
2	Air filter difficult to remove due to gas line placement - unit closes to attic access	6					
3	Duct work in attic pinched in 2 or more locations	7					
4	Air differential tested within standards - 16 degree differential	8					
	D AIR	₹ F	LTERS				
1	Difficult to remove near side unit filter due to gas supply line - repair	5					
2		6					
3		7					
4		8					
	E WALL AND/O	R	LOOR HEATERS				
1	NONE PRESENT	5					
2		6					
3		7					
4		8					
	F THE	R۱	OSTAT				
1	Programmable digital thermostats operating on each level of home	6					
2		7					
3		8					
4	Page 17	of 3	4				
	ŭ						

5	<mark>10</mark>				
	G EVAPORATOR COOLER				
1	NONE 3				
2	4				

	H DUCTS				
1	Low or no air flow was observed - Lower bedroom (quest)	5			
2	Recommend an evaluation of air flow and balance system by a qualified HVAC technician	6			
	Collapsed / kinked ducting observed by squeezing the duct inside truss members and home IT cable restrictions - repairs needed ot allow proper air flow to all serviced areas.	7			
4	Spare carpet crushed one air duct in attic	8			

	I GAS SYSTEMS			
1	All gas lines were tested with no presences of leaks detected	5		
2	Correct plumbing noted to include gas line drip loops	6		
3		7		
4		8		

REMARKS:

Several air ducts were restricted due to tight strap hangers, poor strap angles, joist restrictions, cable routing and other obstructions. See photo - Repair

IV. PLUMBING SYSTEMS ADDENDUM PAGES

Report Identification 1220200845Y

The inspection is of the visible portion of the Plumbing Systems at the time of the inspection. The inspection may be limited by vegetation, possessions, limited access, etc. Plumbing systems located in basements and crawlspaces are limited due to obstructions, clearances and installed equipment. The plumbing inspection depicts what was visible and accessible to the inspector. It is not a warranty or a guarantee of whether the plumbing system is watertight or how long it may remain watertight. Past or present leaks are not always possible to determine. If conditions are listed a qualified plumbing contractor should correct conditions and evaluate the plumbing system. Ventilation and exhaust plumbing, are evaluated by means of visual inspection. Standard inspections cover only visual, accessible plumbing. Water supply systems are evaluated from the point of entry for functional flow. Each bathroom will be tested for multiple appliance flow rate to ensure that proper water pressure exist. All faucets will be tested for proper hot water plumbing, flow rates and possible leaks. If any conditions / defects are noted it is always advisable to have a licensed qualified technician review possible leaks. Septic systems and water wells are inspected for an additional charge. Typical Septic systems are designed to dispose of 150 gallons/bedroom/day. We offer visual, tank, leech field, load and dye test for your septic system. Well water & pump systems are inspected for an additional charge, test include visual, equipment and eight water quality

A WATER SUPPLY SYSTEMS:				
The home is plumbed into the public water supply system. The home's water supply system was inspected from the meter into the home with no visible leaks detected.	5			
2	6			
3	7			
4	8			
B FI	ΧTΙ	JRES:		
All fixtures were installed according to manufactures		5/120.		
specifications	5			
2 No current or previous leaks noted	6			
3	7			
4	8			
C BATHRO	OON	I FIXTURES:		
Master bath tub cold water will not open fully due to spout	5			
2 No current or previous leaks noted	6			
Trim in several locations around the bathroom counters	7			
requires caulk and repainting				
4	8			
		UDDV		
D L	AUI 4	NDRY		
No current or previous leaks noted It is recommend to observe the laundry hose bibs for future	4			
corosion build up.	5			
3	6			
	WA	TER PRESSURE		
1 50 PSI measured at both exterior hose bibs and interior faucet	2			
heads.				
F HYDR	2O-1	THERAPY		
All fixtures were installed according to manufactures				
specifications	5			
2 No current or previous leaks noted	6			
Recommend flushing jets and internal pumping mechanisms	7			
monthly with a sanitizing solution				
4	8			

	H I	DR	AINS
_	All household drains functioning within standards, no current	_	
1	or evidence of past leaks detected.	5	
2	1	6	
3		7	
4		8	
	I SEPT	TIC	SYSTEM
1	NONE - Public sewer system	5	
2	1 to the sever system	6	
3		7	
4		8	
-			
	J WA	TEF	RWELL
1	NONE - Public water system	6	· · · · · · · · · · · · · · · · · · ·
2	TVOIVE - I done water system	7	
3		8	
4		9	
5		10	
J		10	
	K WATER HEA	1TI	NG FOLIIPMENT
		``	NO EQUI IIIENT
	Horizontal piping from hot water heaters were not insulated,		
1	this can cause excessive attic pipe condensation and can result	4	
	in energy lost from the hot water system.		
	Recommend insulation of all supply and distribution lines to		
2	conserve energy and reduce condensation	5	
3	conscive energy and reduce condensation	6	
3		U	
	L VEN	ITI	LATION
1	Adequate plumbing ventilation was observed.	6	
2	riacquate prantong ventriation was observed.	7	
3		8	
4		9	
5		10	
	M EXHAI	JST	T VENTING
	All parts of exhaust ventilation system functioning within		
1	standards	5	
	Proper strapping was used to secure vent piping.	6	
3	Troper strupping was used to seedile vent piping.	7	
4		8	
-			
	N FL	UΕ	VENTS
1	Proper flue ventilation systems installed.	5	
	Flue vents are intact and adequately secured as required.	6	
3	and a second control of the second control o	7	
4		8	
	O WAS	STE	VENTS
1	Droper wests ventilation installed throughout home system	5	
1	Proper waste ventilation installed throughout home system		
	Proper sized waste piping used	6	
3		7	
4		8	
4			

REMARKS:

The home's overall plumbing systems are installed correctly and functioning as intended. It is recommend to consult a

licensed plumber to make any future plumbing repairs or upgrades.

V. APPLIANCES ADDENDUM PAGES

Functions within manufactures standards

Report Identification

1220200845Y

The appliance portion of the inspection is a visual and functional test of all available and operational appliances within the property at the time of the inspection. The inspection may be limited by possessions, personal use, limited access, etc. Inspections are limited due to obstructions, clearances and household or package household items. Only appliances that are present, functioning and properly equipped will be tested. The inspection is not a warranty or a guarantee of whether the appliance is totally free of defects or how long it may remain in its inspected state. Past repairs will only be noted if they are visibility present or disclosed by the current owner. If conditions are listed a qualified appliance contractor should correct or replace the current appliance. Standard inspections cover only primary household appliances and do not cover specialty equipment. Each appliance has a specific number of test designed and accepted to test and evaluate the functionality of the appliance. Inspections are limited by the availability of a electrical supply and contingent upon proper installation. We always recommend routine maintenance and proper care. It is advised to follow all manufacture's guidelines. If any conditions / defects are noted it is always advisable to have a licensed qualified technician review and or correct the discrepancy.

	A DISHWASHER:				
	Functions within manufactures standards	5			
	No leaks observed - operates through all cycle settings to	6			
2	include heated wash and dry cycles.				
3		7			
4		8			
	B FOOD WA		E DISPOSER:		
	Functions within manufactures standards	5			
	No leaks observed - operates through all cycle settings	6			
3		7			
4		8			
	C STOVES	A١	ID RANGES:		
1	Functions within manufactures standards	5			
	Oven measures 354 degrees when set at 350 degrees for	_			
٠,	testing.	6			
3		7			
4		8			
	D MIC	CRC	DWAVE		
1	Functions within manufactures standards	4			
	A 16 oz cup of water reaches boiling point when heated at the				
	microwave's highest power level and heated for 2 minutes.	5			
	inicrowave's highest power level and heated for 2 minutes.				
3		6			
	E TRASH	_	DMPACTOR		
	NONE	4			
3		6			
3		0			
	F WHOLE HOUS	ΕV	ACUUM SYSTEMS		
1	NONE	4			
2	· - ·	5			
3		6			
	G GARAGE D	00	R OPERATORS		
			It is recommended by the manufacture to maintain all opener		

and gargage door hardware in proper maintenance conditions to include lubrication and parts replacement when needed.

2	The auto reversing device on the automatic garage door opener was operational	5	Auto reversing safety photo eyes should be maintained in proper alignement and 6" off the garage foundation floor.
1	The garage door auto reverse tension level is set at the desired tension reverse setting.	6	

	H DOOR BELL AND CHIMES				
1	Functions within manufactures standards	3			
2		4			

	I DRYER VENT			
1	Proper venting observed - vented to outside through utility room wall	3		
2		4		

	J OTHER APPLIANCES		
Ī	1 Cabinet damage observed	4	Kitchen trim issues - see remarks in this section - item J3
	2 Cabinet door needs adjustment.	5	
	The finish on the cabinet kick plate is damaged to the left of stove.	6	

REMARKS:

Quarter round at base boards of stove cabinets are of a different type than the rest of the kitchen cabinets trim. All appliance repairs should be repaired by a licensed manufacture repair technician.

VI. OPTIONAL SYSTEMS ADDENDUM PAGES

Report Identification 1220200845Y

The inspection is based on the visible portion of optional systems identified for inspection.

Only fully installed systems will be inspected for operation purposes. Some systems require specialized and/or detailed testing to include the use of special instruments and/or kits. It is not a warranty or a guarantee of whether the system is flawless or how long it may remain operation. The inspection merely relays the current operation condition at e time of the inspection. If conditions are listed a qualified contractor should correct conditions and evaluate the system for additional problems or conditions which may make the system unsafe to operate. Some specialized test may require additional time to reach and/or evaluate the results to determine functionality of the system. We always recommend periodical servicing of household systems and evaluations by trained specialist is issues occur. If any conditions / defects are noted it is always advisable to have a licensed qualified technician review and or correct the discrepancy.

	A IRRIGATION - LAWN SPRINKLERS		
1	Leaking pipes observed	4	See remarks below
2	Adjustment of spray pattern needed to operate properly.	5	
3	System is over spraying onto structure, immediate repairs and spray head adjustemnet required.	6	

	B SWIMMING I	PO	OLS - SURFACE:
1	Swimming Pool surface and decking is at least 5 feet from main structure	5	
2	Decking does not interfere with drainage from slab, swimming pool perimeter is installed with in-deck drainage compartments which are functioning as intended.	6	
3		7	
4		8	

	C SWIMMING POOLS - GENERAL:		
1	Overall condition of pool was like new and properly maintained	5	
2	Pool was secured from outside access with a privacy fence of at least 6 feet in height.	6	
	Pool fencing gates were maintained with self-closing and self- latching gate hardware.	7	
4		8	

	D SWIMMING POOLS - ELECTRICAL		
1	Electrical wiring was bonded and grounded	5	
7.	Wiring was of proper sizing, electrical breakers were of correct sizing	6	
	All pool electrical outlets were GFCI protected and functioning as intended.	7	
4		8	

	E SWIMMING POOLS - PIPES & VALVES		
1	All valves were functional	5	
2	No visible plumbing or valave leaks observed	6	
3		7	
4		8	

	F POOL FILTERS - SKIMMER		
Г	Skimmer was clean and had proper suction flow	6	
	The pool bottom fliter covers were constucted of approved double anti-suction covers	7	
	3	8	

	G SECUF	RITY	SYSTEMS
1	The home was equipped with a monitored home security system, but these systems are not inspected during a normal home inspection.	8	
2	Consult the home security system installer and monitoring compny for system servicing, repairs and upgrades.	9	
3		10	
4		11	
5		12	

	H FIRE SPRINKLERS		
1	NONE 5	5	
2	6	<mark>5</mark>	
3	7	7	
4	8	3	

REMARKS:

Rotating sprinkler in rear yard, directly in front of back porch will not rotate, needs adjustment. Right side of home, near flower bed, sprinkler line is leaking or sprinkler head is missing. Rear sprinkler system is spraying over on home window, spray head needs adjustment.

Report Identification

Wall damage - left wall at entrance in home fover



Several interior door trims need caulk and repainting



Garage door dead bolt doesn't close engage into door framing and wall stud



Utility room light switch needs caulk



Hallway wall to first floor bedroom has paint runs



Living room wall has bow in sheetrock above arched entry to bedroom



Trim in several locations around the bathroom counters requires caulk and



Master bath tub cold water will not open fully due to spout



Several ceiling - wall junction cracks noted in master bedroom ceiling



Void (gap) at register in middle bedroom



Trim damage to pantry door



Several gaps at base & tops of wall / cabinet iunctions in kitchen & wet bar



Report Identification

Caulk needed at window in formal dining



Kitchen cabinet damage and quarter round doesn't match



Adjust cabinet door at left of stove



Gap at cabinet crown molding and wall



Bathroom cabinet door needs adjustment - second floor



Light in upstairs bathroom not functioning



Gap in upstairs attic door access



Restriction of A/C supply ducts



Gas line blocks filter removal - near side unit



Cable restricting air flow



Another cable restricting air flow



Spar carpet in attic crushing air vent flow



Report Identification

Garage attic access door damaged




Stress crack in garage ceiling perpendicular to attic access



Another photo of ceiling crack in garage



Gap in ceiling at garage light - garage door



Pine needles in gutters - recommend gutter guards



Sprinkler head exposed on left side of home



Gap in ceiling trim - back porch



Gaps in trim caulk on back porch



Hole from missing sprinkler head or leaking pipe - front right of home



Same hole with sprinkler system activated



Sprinkler spray onto rear window - backyard



Center rotary head needs adjustment - back vard



Report Identification

Excellent yard sloping to allow proper drainage from slab



Larger trees are planted at least 20ft from



Gutters and landscaping do not block flow of surface water



Excellent use of stones & lava rocks to reduce insect attraction



Excellent slope and grading from slab to complement drainage



Vegetation is used sparingly to allow ventilation and sunlight exposure



Pathway is clear, lighted and unobstructed - note use of storm door



Note how landscape is maintained at least 3-4 inches below top of slab



Excellent use of storm door and window treatments



Pool decking allows proper drainage away from home



Pool fountain functions as part of the pool circulation system



All valves, jets and skimmer functions within manufactures standards

